CERTIFICATE

This is to certify that

METALSYSTEM srl

Has been inspected and evaluated during the qualification process according to

Norsok Standard M501 Edition 6 February 2012 and Technical and professional requirement TR0042 Final Ver. 5

SYSTEM 7B - STAINLESS STEEL SURFACES

And has been found according for what concern:

- Documents
- Equipments
- Personnel qualification
 - Surface preparation
- Paint application tecnique
 - Inspection instruments
- Inspection and testing activities

Tester: NACE inspector: **Ms. Mihaela Bazon**NACE certified coating inspector Level III # 44117

Place: Metalsystem srl facilities located in Gavirate (VA) Italy

Date: 21 February 2018

Tester Signature

Metalsystem QA Manager Signature

CERTIFICATE

This is to certify that Mr.

LEONARDO OSSOLA

Employee of Metalsystem srl Via Rovera 42/A – Gavirate VA - Italy

Has been evaluated according to
Norsok Standard M501 Edition 6 February 2012
and Technical and professional requirement
TR0042 Final Ver. 5

SYSTEM 7B - STAINLESS STEEL SURFACES
during the qualification process of System 7B and has been qualified as

Blasting operator

he has demostrated to have knowledge about
- Surface preparation
- Coating materials use and application techniques
- Use of sandblasting equipment
- Health and safety hazard and use of protection equipment

Tester: NACE inspector: **Ms. Mihaela Bazon**NACE certified coating inspector Level III # 44117

Place: Metalsystem srl facilities located in Gavirate (VA) Italy

Date: 21 February 2018

Tester Signature No. 1 NACE TO ATING NO. 1 NS. PERTURE W. 144117

Metalsystem QA Manager Signature

CERTIFICATE

This is to certify that Mr.

PIERANTONIO CERRONE

Employee of Metalsystem srl Via Rovera 42/A – Gavirate VA - Italy

Has been evaluated according to
Norsok Standard M501 Edition 6 February 2012
and Technical and professional requirement
TR0042 Final Ver. 5

SYSTEM 7B - STAINLESS STEEL SURFACES
during the qualification process of System 7B and has been qualified as

Paint operator

he has demostrated to have knowledge about
- Surface preparation
- Coating materials use and application techniques
- Use of coating equipment
- Health and safety hazard and use of protection equipment

Tester: NACE inspector: **Ms. Mihaela Bazon**NACE certified coating inspector Level III # 44117

Place: Metalsystem srl facilities located in Gavirate (VA) Italy

Date: 21 February 2018

Tester Signature

